

Oil Field Environmental Incident Summary

Incident: 20150528121336 **Date/Time of Notice:** 05/28/2015 12:13

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: ERRMU 2-18

Field Name: ROUGH RIDER

Well File #: 7483

Date Incident: 4/28/2015 **Time Incident:** 10:30

Facility ID Number:

County: MCKENZIE

Twp: 145

Rng: 100

Sec: 18

Qtr:

Location Description: Spill was approximately 1000 feet off of the location pad.

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	2	Gallons				

Description of Other Released Contaminant:

2 gallons of emulsion and 10 cubic feet of gas released.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Unknown

Potential Environmental Impacts:

N/A.

Action Taken or Planned:

The flow line has been repaired.

Wastes Disposal Location: Contaminated soil has been hauled to an approved disposal.

Agencies Involved:

Updates

Date: 5/28/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to other causes, ran off location. Followup is necessary.

Date: 6/15/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume: 2.00 gallons

Updated Other Contaminant emulsion and 10 cubic feet of gas release

Notes:

NDDH inspector arrived onsite at 9:30am. Weather was sunny with wind out of the south at 20 mile/hour. The area of impact is located south of the pad about 1000ft. It has been scraped and cleaned up. Area surrounding the site is badlands terrain and no water way was impacted by the spill. Due to rain in the past week, a puddle of water was standing in the location where the spill clean-up occurred. Conducted a chloride strip test on the standing water located on the location and it came back as less than 31ppm. No additional follow-up is required.